

Do. of House
Do. of excess
Do. above Cr

TELEGRAMS, "REGISTER, NEWCASTLE"

TELEPHONE: CITY 528, CENTRAL 1528.



Wreck 5

WRECK BOX

No. 5 (Top)

Lloyd's Register of Shipping.

Collingwood Buildings, Newcastle-on-Tyne.

LLOYD'S REGISTER,
LONDON.

12th September 1917

REC'D 13 SEP 17

Reference

The Secretary
London

Sir,

In reply to the enquiring by
the Classification Letter of the 11th inst
regarding the Steamer "Beaumaris"
Rue Rpt No 70199. I beg to inform
you that the rivets in the hull
under laps of the bridge side plating
and strake below sheer are spaced
3½ diameter apart, this error is
reported.

The double bottom under
the boiler is not watertight, the
margin plate being pierced as
approved per Gent's Letter dated
1st January 1916. This tank was
not tested.

I am Sir
your obedient servant
H. C. D. Ireland

W951-0054

Referred to the Outer Ship Surveyor.

SEP 13 1871
also for Mr. A. A. Rice to note.

M
13 9 11

13 9 11



© 2021

Lloyd's Register
Foundation

This ve
les and the
classed

Dec

tudinal

ing: Table

verse No

The endorsement to
to bring out clear
presented in the e

arks of the O

NAME

at Ship Survey