

F.E.

Received by Chief Ship Surveyor

16.1.17.

Received from Chief Ship Surveyor

VESSEL'S NAME

Steel S.S.

Clan Mackay

Rpt.

Nive

No. 69515

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

84.16

Depth "d"

18.

Framing: Table No.

3. page 15

Description

Bulb Angles

Longitudinal No.

35298.

Proportions

Length

10.76

Depth

Shelter

Deck Sheerstrake

as per Rule

Largo battens are not fitted in the Shelter Dk tween decks.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✕ 100A.1 (Steel) Shelter Deck with freeboard," as recommended. The Summer freeboard of 11.3. from centre of disc to top of statutory deck line at Shelter deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

✕ 100A.1 (Steel) "Shelter Deck with freeboard".

2 Dks. (Steel) & Shelter Deck. (Steel)

cell DB. 367' - 12306 DT a 25' 955L. A.P.T. 124E.

FK. 7 BH Com. Lloyd's Reg. F m Shelter Dk 34'.

Certificate to be endorsed "Largo battens not fitted in Shelter tween decks, and a notation to this effect entered in the Register Book."

The Surveyor should be requested to state whether all battens in way of Dk. is W.T. has been tested as required, also the length of same.

W953-0078 1/2

© 2020

Lloyd's Register
Foundation

The Surveyor should be informed the approved plans
of steamfurnaces & other details. plans should
be sent with the reports of the sister vessel.

M
16.1.17



© 2020

Lloyd's Register
Foundation

W953-0078 2/2