

Do.  
Do.  
Gr  
Les  
L

by Chief Ship Surveyor 1. 10. 14 Received from Chief Ship Surveyor \_\_\_\_\_

L'S NAME M. S. Peeman Rpt. Sld No. 26242

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey First entry

It is submitted the Underwriters Surveyors be informed that it is concluded that the tank margin plates are .46 thick and that the rivets in the frames are spaced as required by the Rules

Lr. 2. 10. 14

M. W. W.  
2. 10. 14  
E. G. S.



© 2020

Lloyd's Register  
Foundation

W954-0120