

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 9th Jan. 1917 When handed in at Local Office 9th Jan. 1917 Port of Barry

No. in Reg. Book. Survey held at Barry Date, First Survey 4 last Last Survey 3rd Jan. 1914

S.S. ARDGASK Master

Built at Port Glasgow By whom Russell & Co. When 1916

Owners Lang & Fulton Ltd. Port belonging to Grunoch

TONNAGE:-
GROSS 4540
UNDER DK. 4322
NET 2845

Surveyed Afloat or in Dry Dock? Yes Name of Dock No. 2 Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet; }
total capacity tons. FPT tons; APT tons; MT feet tons. }

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys. Year Assigned now expired. Machinery and Boiler Surveys (including date of N.B., if any).

100 A.1

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Completion.

Tunnel watertight door examined, and tested.

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Felt.) When put on, Month Year
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	Boats
Waterways	State if Tanks now tested	Scuppers	Masts, Yards, &c.
Coamings	Bulkheads	Cargo Hatchways	Condition, how ascertained
Beams & Fastenings	Ceiling	Hatches	(State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Planking of Wood Vessels	Sails
Caulking of ditto	Rudder	Caulking	Equipment letter
Rivets	Steering gear and its connections	Treenails	Anchors, No. of
Breasthooks & Crutches	Windlass	Breasthooks & Stemson	Cables (State if now ranged)
Transoms	Have Pumps now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	" length size (on board)
Frames	Have Sluice Valves now been examined and found efficient?	Timbers of Frame at openings ditto	" Rule length size
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Ditto ditto at other places ditto	Hawser & Warps
Floors		Stringers, Clamps & Shelves ditto	Standing & Running Rigging
Keelsons		Salting (State if examined.) ditto	

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,11," or "to remain as classed and to have record of survey, 1,11, and the notations of ss No. 1-11 and ptND11, &c."

The above is forwarded for the information of the Committee.

Survey Fee (per Section 22)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 22)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute FRI. 12. JAN. 1917

Character Assigned

Thomas W. C. Napier
Surveyor to Lloyd's Register of British & Foreign Shipping.

