

Inspected by Chief Ship Surveyor 14. 4. 19

1

VESSEL'S NAME *St. S. Ardgartan*

Received from Chief Ship Surveyor 17 APR 1919

Rpt. *SW.* No. *14773*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/02.)

Name of Surveyor DAMAGE.

Damage through *Collision*

(see Rpt. no. 10739)

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	<i>1</i>						
Removed and faired } or repaired.....	<i>1</i>						
Faired or repaired } in place.....	<i>2</i>	<i>4</i>					

Other items:-

Vessel examined in Dry Dock. The bottom revealed a minor repair effected.

It is submitted the vessel is worthy to remain as classed with record of Survey *4-19* as recommended *Without special conditions*

100 A.1
4-19 SW. } Without
} Ele

RA
17-4-19
© 2020

The Certificate of Classification, to be endorsed "Cargo battens not fitted," and the same notation to be printed in the Register Book.

