

at to Chief Surveyors 31.7.18

Received from Chief Surveyors

VESSEL'S NAME

SR % Ardgarhan

Report

Enk

No. 17328

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Signature of Survey

2 Entry.

When due

The hand pumps to holds have been dispensed with as approved.

÷ 100 A1 (Steel)

1 DK. (SR) "Well DK"

Cee 10B 190' 395 t. APT 85 t.

FK. 4 BH. Cem. 2 Lloyds A+CP. Q 79'. B 48'. F 28'.

The Certificate of Classification, to be endorsed "Cargo battens not fitted," and the same notation to be printed in the Register Book.

W968-0109


© 2000 MEI.

Lloyd's Register
Foundation