

Do. of Poop 104.84
Do. of R.Q.Dk. 60.92
Do. of Bridge House 38.10
Do. of Forecastle

upper deck beams at side..... 74.00
Transverse Number.....

Built at
When built
By whom
Owners
Managers

COPY.

Lloyd's Register of British & Foreign Shipping,

71, Fenchurch Street, E.C.

Received by Chief Ship Surveyor 23.5.14

VESSEL'S NAME *ARUM*

The remarks of the Chief Ship Surveyor are as follows

23rd May, 1914.

No. 66117
Commitment

Nature of Survey

Dear Sirs,

M. With reference to your First Entry Report No. 66117 on the new Motor Vessel "ARUM", I have to request that you will be good enough to let me know, by wire, whether you are correct in reporting the butts of the 2nd strake below the sheer as treble riveted in view of the breadth of the strake shewn in the section as built and the amendment in red on the approved sketch of midship section.

ect

Section.

I am, Dear Sirs,

Yours faithfully,


Secretary.

Dr. 23.5.14

The Surveyors,

NEWCASTLE-ON-TYNE.

M T/S for (oil engine)



© 2020

Lloyd's Register Foundation

INNER BOTTOM PLATING, breadth and thickness of Middle Line Strake		40	46	40	46
in Engine and Boiler space		1.00	8.46	1.00	8.46
Remainder in Holds.....		✓	38.34	✓	38.34

Third Deck Stringer Plate
Angles on ditto, No.
Tie Plates, outside H
Deck * Material and