

31229 on the Machinery of the Wood, Iron or Steel S. S. Antonio Master
Tonnage Gross 2343 Net 1441 Vessel built at Pt Coquitlam, B.C. By whom Pacific Construction, Whse
276 Engines made at Seattle By whom Puget Sound Dry Dock Co. Depot

Port. GIBRALTAR.

17th. March. 1920.

THIS IS TO CERTIFY that

I, Engineer Captain I.J. Stephens. C.E.B., R.N.

the undersigned Surveyor to this Society did at the request of the Agents, The London Coal Co., Ltd., and with the consent of the Master, survey the boilers of the Greek S.S. "ANTONIO".

Defects. Tubes of Starboard Boiler bulged and leaking.

Recommend. Six tubes that are bulged should be plugged: a water test of 300 lbs. to be then applied, and any tubes discovered to be leaking should be plugged.

30 No. spare plugs to be supplied.

I. J. Stephens

Engineer Surveyor to Lloyds Register.



© 2020

Lloyd's Register Foundation
Surveyor to Lloyd's Register

W 977 - 0096

TUE. APR. 13 1920

Committee's Minute

Assigned