

Length as per Section 39 250 0 Feet. Inches. Extreme Breadth Outside 11 2 10 3 Feet. Inches.

TELEPHONE: SE MOUR 202

TELEGRAPHIC ADDRESS:
"REGISTER" VANCOUVER
CODE: A B C 5TH EDITION

Lloyd's Register of Shipping

BRITISH COLUMBIA

802-3 YORKSHIRE BUILDING

VANCOUVER, B. C., June 28th. 1919.

Secretary,
L's Register of Shipping,
7inchurch Street,
Ln, E. C.

Initial S.

DeSir:-

We are in receipt of your letter of
thed. instant, with enclosures for which we are obliged.

With reference to our Vancouver Report
No. 10 on the Wood Steamer "ANTONIOS", we beg to inform you
that the sizes of the middle line keelsons are as shown on
approved plan forwarded with First Entry Report, also that
the ceiling between the upper and lower deck beams is 8"
in thickness as stated on approved plan.

I am, Dear Sir,

Yours faithfully,

John. Whitehead

JWJH



© 2020

Lloyd's Register
Foundation

W977-0099

The Ceiling, Lower Hold, and between Decks of Douglas Fir
FASTENINGS. To Hold Beams With 4-1 1/4 galv'd screw bolts and nuts through
Shelf Pieces and Clamps of Douglas

Referred to the Chief Ship Surveyor

7th Dec

JUL 15 1915

RR.
17.7.19

J. E. P.

© 2020

Lloyd's Register
Foundation



Received by Chief

VESSEL'S N

The remark

Nature of Survey

IS OF TIMBER

FACE

Length as per Section 39

249

250

Official
Register Tonnage, as a Steamer
not on the Beam.

INSIDE.
The Ceiling, Lower Hold,
FASTENINGS. To 1
and shells.