

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Single Acrow M.V. "LADY GLANELY"

Rpt. Sld. No. 32378

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

1st Long. No.	15463	Depth "d"	25.44.
2nd Long. No.	39420	Proportions = $\frac{L}{D}$	11.196
Framing Bulb angle frames as approved	Sheerstrake	As approved	

Tonnage opening fitted.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ~~100A1~~ "With Freeboard "

The Summer Freeboard as shown on the attached extract from the Freeboard Verification Form, now marked on the vessel's sides, to be inserted in the classification certificate and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying extract, to be inserted in the certificate of classification.


1 Dk. and Shelter Dk.

Cell.DB 357' 1318t, MT 32' 1350t, FPT 85t, APT 160t.

FK, 7BH(Coll.BH to Shelter dk., 6BH to 2nd Dk.) pt.com.,
Lloyd's A & CP.

F 43'.

O.L.447' -7"



© 2020

Lloyd's Register
Foundation

W433-0103

D.O.

Handwritten signature



© 2020
Lloyd's Register
Foundation

33
68