

B. 2m.11.29.

REEBOARD REPORT on the

T.M.V. "Innisfallen"


It is submitted the Surveyors be requested to state how the registered depth is arrived at, as it would appear that this should be 14.92 instead of 15.25.

They should also state the character and extent of all sheathing on the foreboard deck, and should forward a sketch of the portable covers over the forward and after wells, showing how these are secured and how the tarpaulins are fitted over the centre portions.

They should state if any freeing-ports are fitted above the upper deck.

M.R.

22-4-39



© 2020

Lloyd's Register
Foundation

W984-0059