

REPORT of SURVEY for REPAIRS, &c.

Writing Report... When handed in at Local Office 10 MAY 1920 Port of NEWCASTLE-ON-TYNE
Survey held at North Shields Date, First Survey 29 April Last Survey 5 May 1920
on the Wood, Iron or Steel Sps "Jacobus" Master

TONNAGE:- Built at Hull By whom Livingstone & Cooper Ltd YEAR 1920 MONTH 3
GROSS 1262
NET 1088
DECK 756
Owners
Port belonging to
Owners' Address Livingstone & Cooper Ltd Hull (Yard No 175)
(if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage
= Cell DBor DBa feet; uE&B feet; f feet; }
Capacity tons. FPT tons; APT tons; MT feet tons. }
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

First Report, No. Port
Society's Freeboard (if assigned) as painted on Ship and now verified

Where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why he declined?
Was a damage report made by anyone else? If so, by whom?

OR EXAMINATION AS PER RULE, FOR
This vessel arrived in the Tyne from Hessele Hull, to receive her machinery, fitted on board by Messrs The Shields Engineering Co Ltd North Shields. In accordance with letter received from the Hull Surveyors 24 March 1920, to complete the survey for First Entry the following items were completed to my satisfaction.
Casings completed & riveted up
Downton pump & hand pump to fore peak tested
Steering gear & W.T. door tried & found satisfactory

| DAMAGE REPAIRS :— | Plates. | Frames. | R. Frames. | Floors. | Beams. | Str. Plates. | Dk. Plates. | Other Items :— | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|------------------------|-----------|----------------------|--|---------------------------|-----------|--------------|-------------------------------------|----------------|-----------------------------------|----------|---|---|--|-----------------------------------|-----------------------|----------------------------------|----------|-----------------|---------|--------------------------|----------------|-----------------|-----------------------------|--------------------------------------|------------------------------------|-----------------------------------|----------------------------------|---------------------------------------|---|-------|-------------------|---|-------|------------------|-----------------|------------------------------|---------------------------|------------------|----------------|----------------------------|
| and Fair'd or Repaired | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| Repaired in place | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| DITION OF THE | Stringers | Inner Bottom Plating | State if Tanks have been examined inside | State if Tanks now tested | Bulkheads | Ceiling | Cement or Asphalt (State which.) | Rudder | Steering gear and its connections | Windlass | Have Pumps now been examined and found efficient? | Have Sluice Valves now been examined and found efficient? | Have Watertight Doors now been examined and found efficient? | Dblg. Plates under Sounding Pipes | Engine Room Skylights | Coal Bunkers, Open'gs, Lids, &c. | Scuppers | Cargo Hatchways | Hatches | Planking of Wood Vessels | Caulking ditto | Treenails ditto | Breasthooks & Stemson ditto | Transoms, Pointers, & Crutches ditto | Timbers of Frame at openings ditto | Ditto ditto at other places ditto | Stringers, Clamps & Shells ditto | Salting ditto (State if examined.) | Copper, or Y.M. of Wood Vessels (State if on Fell.) When put on, Month Year | Boats | Masts, Yards, &c. | Condition, how ascertained (State if wedges removed) | Sails | Equipment letter | Anchors, No. of | Cables (State if now ranged) | length size (on board) | Rule length size | Hawser & Warps | Standing & Running Rigging |

Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptd15, &c."
This report is for the information of the Committee

Section 28) Fees applied for, 10
Repair Fee (if any) Received by me, 10
Expenses (if chargeable)
Surveyor's Fee (if any)

Committee's Minute
Character Assigned See First Entry report