

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Stl S HINDPOOL Rpt. Hpl No. 16637

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

P. Long

Transverse No.

11930

Depth "d"

25.69

Framing: Table No.

Description

Channel frames as approved

2<sup>nd</sup> Longitudinal No.

33512

Proportions

Length

Depth =

13.75

Deck Sheerstrake

as approved

Revised Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ 100 A. I. (Steel)

1 D<sup>c</sup> (Stl)

Cell D.B. 359' 14025, F.P.T. 1885, A.P.T. 1905

F.K., 6 B.H., Cem, Lloyds ARCP

P 30', B 229', F 41'.

8/6.6.28



© 2020

Lloyd's Register  
Foundation

W984-0194