

TELEPHONE: CENTRAL 6610. & 6611.



Lloyd's Register of Shipping,

Ocean Chambers, Lowgate,

Hull, 5th March. 1930.

Reference



Dear Sir,

With reference to your classing letter dated the 4th instant in regard to the First Entry Report No.40622 on the "HOLME FORCE", we beg to inform you that 6 x 3 x .34 bulb angle stiffeners are fitted in the vessel on 70 frame, as reported, but that these are fitted with bracket attachments top and bottom and form the Rule equivalent size to the stiffeners as approved.

We are, Dear Sir,

Yours faithfully,

The Surveyors,

Per:-

M. Malcom

The Secretary,

LONDON.E.C.3.



© 2020

Lloyd's Register
Foundation

be endorsed "Cargo Stiffeners not fitted" and the same notation to be printed in the Register Book.

It is concluded the size of the bulkhead stiffeners on frame

Referred to the Chief Ship Surveyor.

hms

-6 MAR 1930

Ho.



© 2020

Lloyd's Register
Foundation