


Lloyd's Register of Shipping,

55, Fawcett Street,

Sunderland, 15th September, 1938.



reference

F. Dear Sir,

With reference to your letter of the 12th instant respecting the S.S. "JOSEPH SWAN", we have to inform you that the official number is 166572. *W. C. Huller*

The height of the ventilator coaming on the sloping hatch end coaming, at the forward end of No. 2 hatch is 4'-6" and not 6" as stated in the Rpt. C(11). It is regretted that this error has occurred.

We are, Dear Sir,

Yours faithfully,
THE SURVEYORS,
PER:

W. C. Huller

The Secretary,
LONDON.



© 2020

Lloyd's Register
Foundation

2020-09-15

Referred to the Chief Ship Surveyor.
(Proceeds).

RS

16 SEP 1938

*Noted on
Rt Hon C.B.
16/9/38*

LONDON.
The Secretary.

THE SECRETARY,
LONDON

Dear Sir,

I regret that the error has occurred.

It is not as stated in the B.S. G.I.I. It is
a matter of course of the interest of the
The matter of the certificate concerning the

that the certificate number is 1938/2.

Respecting the B.S. "LONDON" as well as the London

My reference to your letter of the 15th instant

Dear Sir,

LONDON

RECEIVED
LONDON
SEP 16 1938

15th September, 1938.

22, Cannon Street

London



© 2020
Lloyd's Register
Foundation