

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined offered & declined

Society's Freeboard (if assigned)
painted on Ship and now

Was a damage report made by anyone else? if so, by whom? Yes

19th November, 1947.

Dear Sirs,

With reference to Mr. Wilmshurst's enquiry on the telephone this afternoon relative to the Steamer "LANGLEECRAG", I beg to acquaint you that the following is an extract from the report of the Society's Hull Surveyors of their survey carried out on the vessel at that port recently:-

"Condition:- Vessel in drydock, shell plating and rudder cleaned, examined and re-coated. Examination made of decks, casings, hatchways and closing appliances, steering gear, windlass and general equipment.

Repairs W. & T. Rudder gudgeons re-bushed, bilge strake butt rivets (s.s.) built up by E.W., and sundry minor repairs effected.

Annual Load Line Survey carried out concurrently with the above, about 60 hatch wood covers renewed, vent and air pipe plugs supplied, and sundry minor repairs effected."

Yours faithfully,

omsley Steam Shipping Co. Ltd.,
3, Crosby Square,
LONDON, E.C.3.


Clerk to the

think it well to add that a photostat of the Surveyors report, the above is an extract, can be furnished to you if desired at the charge.

Bottom Plating	✓	examined and found efficient?	✓	Stringers, Clamps & Shelves	✓
the Tanks been examined internally	NO.	Air and Sounding Pipes	✓	Salting	✓
the Tanks been tested?	F.P.	Doubling Plates under Sounding Pipes	✓	State if examined.	

the Surveyor
between
the
and, e
lungs
ring
4'
effici
ment
red,
er Items :-
Copper, or
(State if
When fitted
Boats
Masts, Yards
Condition,
(State if
Equipment
Anchors, N
Cables (Sta
" leng
" Rule
Chain Lock
Hawsers &
Standing an
Sails

© 2020



Lloyd's Register
Foundation
W9938-0133