

NET 6087 Managers. Partially submerged Name of Dock Berth 168, Wilmington, Cal. Destined Voyage Marti
Surveyed Afloat or in Dry Dock?

CABLE ADDRESS
KEYTANK

TELEPHONE
WALNUT 2-2964

KEYSTONE TANKSHIP CORPORATION
1015 CHESTNUT STREET
PHILADELPHIA 7, PA.

July 21, 1947

RECEIVED

8 AUG 1947

ANSD.....


Lloyd's Register of Shipping
71, Fenchurch Street
London, E. C. 3.

Gentlemen:

Answering your letter of July 7 we regret
to advise that the "Markay" was abandoned as a total
loss on June 22, 1947, at San Pedro, California, and it
will therefore be in order for you to expunge her from
the Register Book.

Very truly yours,

KEYSTONE TANKSHIP CORPORATION



Chas. Kurz
Vice President

ml



© 2020

Lloyd's Register
Foundation

W 996-0072

ification (w
gister Book &
of (incl
Sea. *LM
T
roleum
oil fuel
50°F.
assigned) as
ow verified
ited Sta
Associ
e, while
June 2
Exposed
urned.
ates & f
ackled an
ack on d
ers for
or Y.M.
ate if on Felt.)
fitted, Month
Yards, &c.
on, how ascertain
ate if wedges rem
ent letter
s, No. of
(State if now ra
length
(on board)
Rule length
ocker
& Warps
g and Running Rip
Register Book cor
lassed and to h

Referred to Mr. Spry.

Please return to
Mr. Hudson
Secretary etc.
WHR



© 2020

Lloyd's Register
Foundation

on or below the space for Committee's Minutes.)

If so, is the Report sent now or when will it be sent?

NET
Surveye
CellDB
total ca
N.B.
Last
Periodical
completi
extent of
should I
summariz
should I
inspectio

In damage
offer
L. An. A
REPAIRS,
Cargo
Cause
Bow an
hull a
House
Poop a
Foreca
No. 3 C
part m
The ve
and at
SUMMARY

Referenc
Remover
Faird
PRESENT C
Decks
Gaulking of D
Coainings
Beams & Fasten
Outside Plating
" "
Frames
Reverse Frames
Longitudinals
Transverses
Floors
Keelsons
Stringers
Inner Bottom P
Have the Tanks
Have the Tanks
General
This Re