

TELEPHONE: SWANSEA 3860.

Reference

16 DEC 1943

Dear Sir,

We are retaining the deferred reports on the Tanker "MARKAY" in the meantime, pending Mr. Stocks's visit for examination of this vessel in drydock, which, it is anticipated, will take place at the beginning of the next week.

Trusting our action in this matter will cause no inconvenience,

We are, Dear Sir,  
Yours faithfully,  
The Surveyors,  
Per:-

The Secretary,  
WOKINGHAM.



© 2020

Lloyd's Register  
Foundation

plating buckled and pierced at forward end of No. 4 wing tank sta

SUMMARY OF DAMAGE REPAIRS:—

Shell Plates.

Frames.

R. Frames.

Floors and  
Bracket Floors

Beams.

Inner Bottom  
Plates.

For temporary repairs:—



H  
R8

16 DEC 1943



© 2020

Lloyd's Register  
Foundation