

2

1500.10.40.

*Empire
Newcomen*

William Gray & Co. Ltd., West Hartlepool.

W 8, 522
Yard No. 1119

F.E.

Wicklow Head

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor..... *1 OCT 1921*

VESSEL'S NAME..... EMPIRE WOLFE Rpt. Hpl No. 18194

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 7595 ✓ Depth "d" -
 2nd Long. No. 21957 ✓ Proportions = $\frac{L}{D}$ to Upper dk 12.65 ✓
 to Bridge dk 9.25 ✓
 Framing Bulb angle frames as approved. Sheerstrake As approved

The tank top plating has been increased in thickness under the hatchways in lieu of ceiling.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A1

1 Dk
 Cell DB 270' 629t, FPT 59t, APT 117t
 FK, 5BH, pt. Cem., Lloyd's A & CP
 P 33' B 82' F 34'
 O.L. 327.9'

u
The class is assigned and maintained upon the understanding that the equipment will be made to accord with the requirements of the Rules when the present state of emergency has passed, and that cargo battens will be fitted at the first available opportunity.

Insert in S.R.L:- (A bower anchor & 45 fms. c.c. to be supplied)
 Cargo battens to be fitted at the first opp.

Stales

© 2020
 Lloyd's Register
 Foundation
 W997-0159
 13.10.41