

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C. 3.

24th March, 1921.

Dear Sir,

S.

With reference to Glasgow first entry machinery report No.40686 on the steamer "DRAMATIST", I shall be glad if you will kindly ascertain from the Surveyors and let me know whether the screw shaft of this vessel is fitted with a continuous liner, two liners, or no liners, as this information is not given on the report.

I am, Dear Sir,

Yours faithfully,

Assistant to the Secretary.

The Secretary,

GLASGOW.



© 2020

Lloyd's Register

Foundation

Angle, Plate, Top Bulb, or Channel	11x3 1/2	3 1/2	11x3 1/2	3 1/2	11x3 1/2	3 1/2
Spacing	53	53	53	53	53	53
BEAMS, Third and Fourth Deck, Single Angle,	11x3 1/2	3 1/2	11x3 1/2	3 1/2	11x3 1/2	3 1/2
Ball Angle Plate Tee Bulb, or Channel	11x3 1/2	3 1/2	11x3 1/2	3 1/2	11x3 1/2	3 1/2
Angles on upper edge	11x3 1/2	3 1/2	11x3 1/2	3 1/2	11x3 1/2	3 1/2
Spacing	53	53	53	53	53	53
POOP DECK SURVEY						
Angle on ditto						
Tie Plates						
Deck, Material and thickness						