

Sent to Chief Surveyor

25097

Received from Chief Surveyor

VESSEL'S NAME

SS Strathleven

Report

Shi No. 007

For the CHIEF SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Rprs
B.S. due 2 97. To be held on return

This vessel was examined by the Hong Kong Surveyor in dry dock in March, 96 and he reported that the edges of the plates at keel and fore foot were chafed, and he recommended a shoe plate ~~should~~ to be fitted when the vessel was next dry docked. Record of Survey 3, 96 was assigned subject to this being done.

The Shanghai Surveyor reported in March last that he had examined the vessel in dry dock, but he made no reference to the above in his report.

The case was before the Committee on the 15th April last and the Shanghai Surveyor was communicated with and record of survey 3, 97 assigned, subject to a satisfactory reply being received from him.

In a letter now received from the Shanghai Surveyor he states ~~that~~ that as far as he recollects he pointed out to the Master that it would be desirable to have a shoe plate fitted on the occasion of the next Special Survey.

It is submitted under the circumstances that action in the matter might be deferred until the S.S.No.2 is held and in the meantime the vessel might be allowed to remain as classed subject to this being done.

100 A 1 }
3.97 Shi. } subject to.



C.H.F.
© 2018
25/6/97
Lloyd's Register
Foundation