

Sent to Chief Surveyor

7.7.97

Received from Chief Surveyor

SEL'S NAME

L.S. Strathleven

Report Shi No. 669

For the CHIEF SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Closing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Closing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

re of Survey

Mrs. I.S.

When due

The Newcastle Surveyors should
be advised as to the matter
of the shoe plate which was
recommended by the Hong Kong
Surveyors to be fitted when
the vessel was next dry docked.
see endorsement dated 25.6.97
In the event of the vessel being placed
in dry dock the stem bush & screw
shaft should be examined. The
annual boiler survey held 11.7.97.

[Signature]

E. J. M.
7.7.97

C. H. J.

[Signature]
8.7.97

For Mr. Mill to Note.

& write back

Lt. 8/7/97 *[Signature]*
8.7.97



© 2018

Lloyd's Register
Foundation