

9 wire
Chief Surveyor

SEL'S NAME

17. 3. 99
LSS Shathleven

Received from Chief Surveyor

Report

Lon No. 60463

For the CHIEF SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

No.

2

SURVEY PARTLY HELD.

10 9)

When proposed to be completed

due

of Survey held, &c.

(K.B. Incl rpt not rec)

It is submitted the owners be informed by wire that the Chain Cables were sauced at St. Johns and cross bunker examined but ceiling in same not lifted as required by rule and this remains to be done.

The Genoa Surveyor should also be similarly advised by wire.

ie + Mr. As Own: 17. 3. 99

C. H. J.
17/3/99

For Mr Hill to note

~~State~~ wire given

17. 3. 99



© 2018

Lloyd's Register
Foundation