

REPORT of SURVEY for REPAIRS, &c.

BOX CASE 40581

(Received at London Office, 20 3 81)

No. in Survey held at London Date, first Survey 3rd Mar Last Survey 26th Mar 1881
 Reg. Book. 505 on the Iron Schooner "Lizzie & Annie" Master J. Hewton
 TONNAGE under Tonnage Deck 99 Built at R. Shields When built 1877 6 MONTH.
 Ditto of Spar Deck, or Awaiting Deck
 Ditto of Poop
 Ditto of Raised Qr. Deck
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 99 Owners J. Slator Port belonging to Boston
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as S^tmer, cut on Bm. 62 Residence
 By whom built Softly Destined Voyage Coaster
 If Surveyed Afloat or in Dry Dock Mountain gridon (State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. 90 A 1 Character in Register Book.
 Last Survey, No. 24238 Port Iron Classed 5.79

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

Through damage by collision
 Stem taken out straightened and refitted. 3 freeboards of
 plating and one bulwark plate on the Starboard side. 4 freeboards
 and one bulwark plate on the Port side renewed, one frame
 set fair. Hawse pipes replaced.
 30 fms of Cable 3/16 Close link No 3392 Tests 7 1/10 Tons and 15 2/10 Tons Lipton Public Machine
 24 Nov 79 E R Sutt Sept 81
 Bow Lusha & Co Stock 4.1.6 No 5713 Test 6.13.3.0 Chester Public Machine 13 Apr 80 A D Jack Sept 81
 Equipment No 3092.
 Not of damage - 2 bulwark plates on the Starboard side new and
 one length of Angle iron under main Rail

Present Condition of the

Decks	Good	Freonails	Rivets	Good	Windlass and Capstan	Good
Waterways	---	Breasthooks and Stemson	---	---	Pumps	---
Comings	---	Transoms, Pointers, and Crutches	---	---	Boats	---
Upper Deck Beams & Fastenings	---	Timbers of the Frame at the openings	---	---	Masts, Yards, &c.	---
Lower Deck Beams & Fastenings	---	Ditto Ditto at other places	---	---	Condition, how ascertained	from Deck
Planksheers	---	Keelsons	---	---	Sails	Good
Sheerstrakes	---	Clamps and Shetfs	---	---	Anchors No. of 2 B. 15 & 1K	---
Topsides	---	Ceiling	---	---	Cables	Complete
Wales	---	Rudder	---	---	Hawsers and Warps	Good
Plank (Bottom) and Counter	---	Copper (or r.m.)	Cement	When put on 1st 79	Standing & Running Rigging	---
Engine Room Skylights	Good	Caulking of	Good	Good	Cargo and Main Hatchways	Good
Coal Bunker, Openings, Lids, &c.	Good	Bottom, Deck, & Waterways	Good	Good	Hatches	Good

General Observations, Opinion as to Class, &c.

She is now in good condition, and in my opinion
 eligible to continue as Classed

The Amount of Entry Fee ... £ : : : received by me, AB.
 " 1/10 Special ... £ 1 : 1 : - Oct 28 1881
 Certificate (if required)
 to be sent as per margin... £ : : : -

(Travelling Expenses, if any, £)

Committee's Minute

Character assigned

Issued 8. July, 1881.

JBW 90A

Will E. Davey
 Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2018

Lloyd's Register
 Foundation