

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 2/10/93 When handed in at Local Office

3/10/1893 Port of Hull

No. in Reg. Book Survey held at Hull

Date, First Survey Sep 29th Last Survey Oct 1893

386 on the Wood, Iron or Steel

(No. of Visits)

TONNAGE

GROSS

UNDER D.K.

NET

Master A. Parker

YEAR

MONTH

Built at North Shields By whom Softay & Co When 1893 6

Owners Boston & London S.S. Llyod's Port belonging to Boston

Grossers' Address

(if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Any dock Name of Dock Smith's Destined Voyage Coasting

WB=DAW tons; f tons; uE&B tons; CellDB tons; FPT tons; APT tons; MT tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER

X for Special Survey
Date of last Survey and of Periodical Surveys

Years of last survey and of last periodical survey

Machinery and Boiler Surveys (including date of X.S., if any).

+ 90 A1 6/90 B55,93

S.S. Hull No 3, 6, 90. Dec 6, 90

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

Last Survey, No. 8014 Port Hull

In a Report also sent now on the Machinery of the Ship?

If not, state whether, and when, one will be sent.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Annual Survey.

The vessel placed in dry dock the bottom examined and found in good condition, the same now cleaned and repainted. The rudder lifted and putty rebrushed.

SUMMARY OF DAMAGE REPAIRS: Plates, Fair'd or Repaired: Frames, ditto: Plates, Renewed: Frames, ditto: Other Repairs.

PRESENT CONDITION OF THE

Decks	good	Transoms, Pointers, & Crutches	good	Copper, or Y.M. (State if on Felt.)	<input checked="" type="checkbox"/>	Hatches	good
Wateryards	"	Timbers of Frame at the openings	"	When put on, Month	<input checked="" type="checkbox"/>	Boats	"
Coamings	"	Ditto ditto at other places	"	Year	<input checked="" type="checkbox"/>	Masts, Yards, &c.	"
Up'r Dk. Beams & Fastenings	"	Keelsons	"	Rudder	good	Condition, how ascertained	"
Low'r Dk. Beams & Fastenings	"	Clamps, Shelves & Stringers	"	Windlass & Capstan	"	Sails	"
Plating	"	Salting (State if examined.)	"	Pumps	"	Equipment letter	"
Planking	"	Ceiling	"	Engines Room Skylights	"	Anchors, No. of	"
Transom Rivets	"	Cement or Asphalt (State which.)	"	Coal Bunker, Open'gs, Lids, &c.	"	Cables (State if now ranged)	"
Breasthooks & Stemson	"	Tanks (State if now tested.)	"	Scuppers	"	" length	"
		Caulking of Bot'm, Dk, & Wat'rwy's	"	Cargo & Main H'tchwy's	"	" Rule length	"
						Hawsers & Warps	"
						Standing & Running Rigging	"

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—".....to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss. No. 1-91 and pND91, &c."

This vessel as far as seen is now in good condition and in my opinion eligible to remain as classed and to have record of Survey 10, 93.

Office Fee (if chargeable) per Scale 14, sec 27	£ : : :	Fees applied for,
Survey Fee (per Section 28)	£ : : :	18.
Special Damage or Repair Fee (if any) (per sec. 28.)	£ : : :	
Travelling Expenses (if chargeable)	£ : : :	18.
Second Surveyor's Fee (if any)	£ : : :	

Is Certificate now required?

Committee's Minute TUES, 10 OCT 1893

Character assigned 90/11

Mach. repair

R. Williams
Surveyor to Lloyd's Register of British & Foreign Shipping.

© 2018

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or cause it to show through to the other side.

If is submitted that
this vessel is eligible
to remain **A.G.** CLASSED.

The hatches and propeller shaft
were removed, and a few
repairs were effected.
None are given.

P.A.
9-10-93



© 2018

Lloyd's Register
Foundation