

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

13th February 1962.

Enclosure.

Dear Sir,

M.S. "LIZZIE & ANNIE"

This vessel's class is qualified with the notation "Special Survey incomplete - class suspended 8.61," and in connection with this case I enclose a copy of a letter from the old Owners and shall be glad if you will contact the Earnbank Sand & Gravel Co. Ltd., ^{+ address} and ascertain their intentions for completing the Special Survey.

To complete the Hull Survey for the notation SS (Dr) 10.59 the following matters require attention:-

TO BE EXAMINED:-

Fore peak space (dry), aft. peak tank; engine space and under engines; anchors and chain cable, mast and rigging, renewal Loadline Survey. Thickness of wood upper deck to be ascertained.

TO BE TESTED:-

Aft peak tank.

In addition ~~this~~ parts previously surveyed at Hull in October 1959 should be examined to ensure that the items are still in good condition.

Continued.



© 2018

Lloyd's Register
Foundation

Continued.

M.S. "LIZZIE & ANNIE"

A complete Engine Survey requires to be held and the screwshaft in way of the oil gland specially examined, and, if found satisfactory, a record of screwshaft examined 10.59 could be assigned.

Your attention is also drawn to the entry in the Special Reasons List.

Yours faithfully,

Clerk to the
Classification Committee.

The Secretary,
GLASGOW



© 2018

Lloyd's Register
Foundation