

Plymouth

12th February 1887

John E. Taylor.

Messrs. Hamson & Baggallay of London.
for the Owners. hold a Special Survey of the Machinery
of the Iron S.S. "Batavia", 999 tons, of London. Thames
Weatherham Master. reported to have sustained damage
whilst on a passage from West Hartlepool to Batavia.
for further particulars of which see Ship's log book
and Master's Protest.

10th February 1887 and subsequently, vessel
then lying in Plymouth Sound, proceeded on board
and found the Low Pressure Cylinder Cover Cracked,
and the Piston broken out on under side about
two feet in diameter.

Recommended that New Low Pressure
Cylinder Cover and Piston be fitted and the Piston
rod put in better to ascertain the truth of same
also that it is expedient to remove broken cover
and Piston with view into repair shop to get details
from the same.

To L.R.C.C.



©2018

Lloyd's Register
Foundation