

Npl 8224

'Bakuin'

3.11.90

Patent cement in flat of bottom
found blistered + repaired with
Portland. Ballast Tanks should
be entirely examined at an early
opportunity.



© 2018

Lloyd's Register
Foundation