

15th November 1890.

Dear Sir,

With reference to the classification in this Society's Register Book of your steamer "BAKUIN", which has recently been under survey at West Hartlepool, I am directed to acquaint you that in view of the patent enamel in the flat of the bottom having been found blistered and been repaired with Portland cement, an early opportunity should be afforded to the Society's Surveyors to re-examine the ballast tanks internally, and I shall be glad if you will kindly let me know when and at what port you can best arrange to have this done.

I am, Dear Sir,

Yours faithfully,

A. Stuart, Esq.

Gt. St. Helen's,

E.C.



© 2018

Lloyd's Register  
Foundation