

the owners representative
proceed on board the steamer
"Batouin" ^{1669/1003} Tonnage of London
when placed in the Trawing dock
of the Hamburg-American Packet
Co at this port for the purpose
of ascertaining the damage
stated to have been sustained
by grounding in the Dardanelles
on her last outward voyage
from Hamburg to Batouin in
ballast. (For further particulars
I beg reference to be made to
the Log-book & Protest.)

The bottom of the vessel
has been examined, found sev-
eral butts slightly strained in
flat of bottom, which is no
importance, except one butt ²¹²
aft. The paint found scratched
off in some places, but else



© 2018

Lloyd's Register
Foundation

the bottom was found in good condition.

The bottom has been repainted, rudder tilted & pintles rebushed, also one butt recaulked as recommended.

The repairs recommended by me have been executed to my entire satisfaction.

Gmül Paderatz

L. 2. 12. 0
Encl. in receipt



© 2018

Lloyd's Register
Foundation