

2462
on file

Hamburg
25th March 1893

Emil Paddcratz

The representative of the
owners proceed on board the
British Steamship 'Bakuin'
106th/1093 Tonn. of London for the
purpose of ascertaining the
damage stated to have been
sustained by grounding in
this port and by proceeding
through heavy ice on her last
passage out to the Black Sea.

For further particulars of
accidents I beg reference to be
made to the Logbook.

The vessel was placed
in Messrs. Blohm & Voß, floating
dry dock for examination, found
the paint partly rubbed off on
her bottom and the brackets of
foreward tank leaky.

I recommended that the
bottom be cleaned & repaired.



© 2018

Lloyd's Register
Foundation

and the forward tank be lightened
and tested as required by the rules.
The repairs recommended
by me have been executed to my
entire satisfaction.

Emil Taddesatz

\$2.12.0
incl. in receipt



© 2018

Lloyd's Register
Foundation