

Sent to Chief Surveyors 20.8.94

Received from Chief Surveyors

No. 2 SURVEY PARTLY HELD.

VESSEL'S NAME S.S. "Bakuin" Report Ham. No. 2971

The remarks of the Chief Surveyor are desired on this Case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.92.)

When due

6.94

When proposed to be completed

3 months time.

Portion of Survey held, &c.

The S.S. No. 2 which became due in June, 1894 was partly held in March last, and has now been further advanced; and to complete the same, the following requires to be done:—No. 2 hold cleared, ceiling lifted, and examination made; ballast tank in same, and tank in E&B. space cleared, examined, and tested; E. & B. bearers and other iron work in E. & B. space examined; mast, spars rigging, and general equipment examined and peak tanks tested.

The Surveyor reports that the main deck plates alongside the engine casing on starboard side and the lower plates in the coal shoot are defective. He recommends that they be renewed or repaired.

The Surveyor reports that the survey will be completed and repairs effected at Hamburg in 3 months time.

It is submitted the vessel appears worthy to remain classed ~~100A1~~ record of survey to be deferred until the S.S. No. 2 is completed.



2018
21.8.94

Lloyd's Register
Foundation