

Sent to Chief Surveyor 23. 3. 95.

Received from Chief Surveyor

VESSEL'S NAME I.M.S.S. "Bakuin" Report Ham No. 3175.

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Docking &c.

Vessel placed in dry dock, and bottom examined. A few rivets renewed.

The Surveyor reports that one plate on the starboard bow in third strake from keel appears to be slightly flawed, but he could not definitely ascertain the nature of the same, and recommends that ~~the~~ This be examined again when next the vessel is placed in dry dock.

It is submitted the vessel appears worthy to remain classed 100A1, "Carrying petroleum in bulk", with record 3,95 Ham. subject to the plate mentioned above being again examined when next the vessel is placed in dry dock.

100 A.1.

"Carrying petroleum in Bulk"

3-95 Ham} Subjective

S. J. M.

©2018  
25/3/95



Lloyd's Register  
Foundation 170