

TUES, 9 NOV 1897

## REPORT of SURVEY for REPAIRS, &amp;c.

Date of writing Report.

18 When handed in at Local Office

H' Nov 1897 Port of Newcastle

Date, First Survey 29 Oct 1897

Last Survey 29 Oct 1897  
(No. of Visits)

No. in Reg. Book. Survey held at North Shields on the Wood, Iron or Steel S.S "Baku Standard" Master

29 TONNAGE:-

GROSS 3708

UNDER D.K. 3335

NET 2375

Built at Newcastle

Owners A. Stuart Mgr

By whom Sir W. G. Armstrong, Ltd.

When 1893

2

Port belonging to London

Owners' Address

(if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Pontoon Name of Dock Smith's Pontoon Destined Voyage

WB=CellDBorDBa feet; uE&amp;B feet; f feet; t tons; FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 59158 Port London

(Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors, Chains, or Hawsers is reported, the particulars of weight or size and test of the articles should be clearly stated, and also the weight or size, &amp;c., required by the Rules, together with the vessel's Equipment Letter, if any. State also the dates and initials of any letters respecting this case.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Special Survey No I Completion.

Please see Newcastle R.R. No 34530.

Vessel placed on the pontoon, bottom examined cleaned and coated as required.

Now done. Double bottom under boilers examined internally and tested. Double bottom under engine and fore peak tank tested. Lower bunkers cleared, examined, cleaned and coated. Water tight doors found efficient. (Has no hand pumps or sluices)

CHARACTER.	YEAR	MACHINERY AND BOILER SURVEYS (INCLUDING DATE OF X.R., IF ANY).
+100A/1	1897	+L.M.C
Shai. dk	3, 97	Carr. Petroleum in bulk Society's Freeboard (if assigned) as painted on Ship and now verified

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
Renewed ... ...								
Paired or Repaired ...								

PRESENT CONDITION OF THE	Good	Good	Good	Good	Good	Good
Decks						
Wateryards	4					
Coamings	4					
Up'r Dk. Beams & Fastenings	4					
Low'r Dk. Beams & Fastenings	4					
Plating	4					
Planking						
Rivets on Planks	4					
Breasthooks & Guttures	4					
Transoms, Seats, & Crutches	4					
Timber of Frame at the openings						
Ditto ditto at other places	4					
Keelsons	4					
Stringers, Gamps & Sheds	4					
Bottoming						
(State if examined.)						
Ceilings	4					
Cement or Asphalt	4					
(State which.)						
Tanks	4					
(State if now tested.)						
Caulking of Bot'm, Dk', & Wat'r'y'a	4					
Copper, or Y.M.	—					
(State if on Felt.)						
When put on, Month	—	Year	—			
Rudder						
Windlass & Capstan	—					
Have Pumps now been examined and found efficient?	—					
Have Sluice Valves now been examined and found efficient?	—					
Have Watertight Doors now been examined and found efficient?	400					
Dblng. Plates under Sounding Pipes	—					
Engine Room Skylights	Good					
Coal Bunker, Open'gs, Lids, &c.	—					
Scuppers	—					
Cargo & Main H'tch'ys	—					
Hatches						
Boats	4					
Masts, Yards, &c.	—					
Condition, how ascertained	from dk					
(State if wedges removed)						
Sails	Good					
Equipment letter						
Anchors, No. of	313 - 16 - 1K					
Cables (State if now ranged)	for Seen					
" length	—	size	—			
" Rule length	—	size	—			
Hawsers & Warps						
Standing & Running Rigging	Good					

## General Observations, Opinion as to Class, Recommendation, &amp;c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1897," or "to remain as classed and to have record of survey, 1897, and the notations of ss. No. 1-97 and p1897, &amp;c."

This vessel being now in a good and efficient condition, and having completed the requirements of the Rules is eligible in our opinion to remain as classed, to have record of Survey 1897 and notation S.S. No 1-97 with removal of name from Special Reasons list.

Office Fee (if chargeable) per Scale IX, Sec. 87 £ 2

Survey Fee (per Section 28) £ 2

Special Damage or Repair Fee (if any) £ 2

Travelling Expenses (if chargeable) £ 2

Second Surveyor's Fee (if any) £ 2

Committee's Minute

Character assigned

No. 1

FRI. 12 NOV 1897

Fees applied for,

18

Received by me,

18

Surveyor to Lloyd's Register of British &amp; Foreign Shipping.

T. Shilton.

B.M.B.D.Y.R.



© 2018

Lloyd's Register Foundation