

Lloyd's Register of British and Foreign Shipping.

PORT OF CONSTANTINOPLE,

Jan^y 2nd 1899

LLOYD'S REGISTER
LONDON.
RECR - 9 JAN. 1899
ANSE

Sir,

Your communication marked (S)
of the 28th just to hand, respecting the
propellor blades of the S. S. "Baku Standard"
860.

The two broken blades, one having 14"
off, & the other 11" were not repaired here.
but it was understood that a new propellor
should be made & fitted on arrival in
the United Kingdom, at end of present
voyage, as the Owners requested that
nothing should be done further than
actually necessary in this port.

Yours Obedient Serv^t.
G. R. Warren
Eng. Surveyor.



© 2018

Lloyd's Register
Foundation

PORT OF CONSTANTINOPLE.

1899

Jan. 2. 99

LLOYD'S REGISTER
LONDON.
RECEIVED - 2 JAN 1899
ANB

of the 26th inst. to hand, respecting the
propeller blades of the S. S. "Robert" (marked 2)

The two broken blades, one having 11" & the other 12" were not repaired but
it was understood that a new propeller
should be made & fitted on arrival in
the United Kingdom, at cost of payment
on account, as the Owners requested that
nothing should be done further than
necessary in this port.

Yours obediently
J. P. Warren
Prof. Carpenter.

Also for Mr. Hill to note
E 9 JAN 1899

a.s.



© 2011
Lloyd's Register
Foundation