

Received by Chief Ship Surveyor 5.6.06

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME M. S. S. "Baku Standard" Rpt. Two No. 51007

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

S.S. No. 3

Nature of Survey \_\_\_\_\_

The S.S. No. 3 has now been held, and the following repairs done (due to wear & tear) :-

4 Reverse frames renewed and several repaired, 1 deck plate renewed and several doubled, other minor repairs done.

It was not considered necessary to drill the plating.

It is submitted the vessel is worthy to remain as classed, with record of Survey 5.06 and notation of S.S. Shl No 3-5.06 as recommended.

100 A 1 Spar dk.  
5.06 Shl.  
S.S. Shl. No 3-5.06

W. S.  
5.6.06

C. H. J.