

IHUR. 29 AUG 1907

Report of Hornby - on - Tyne

Continuation of Report No. 52442 dated

28 AUG 1907

on the

8/8 Baku Standard

alterations, on my first visit to the vessel, but owing to the delay in this matter, the work was finished before its approval.

The amendments as shewn on the approved plan have therefore not been carried out, but the Owner's Superintendent on being informed of the extra size of stiffeners required, states he is prepared to fit equivalent strength on the first occasion when vessel is steamed out and this proposal in my opinion merits the favourable consideration of the Committee.

Approved plans (6in N°) are returned herewith

18.

NOT TO WRITE ACROSS THIS MARGIN.
OR THE SURVEYORS ARE REQUESTED

and when tested and
Superintendent.

where tested and
Superintendent.

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report	Aug 23 rd 1907	When handed in at Local Office	Aug 26 th 1907	Port of Newcastle-on-Tyne	
No. in Reg. Book.	Survey held at North Shields	Date, First Survey	Aug 7 th 1907	Last Survey	Aug 20 1907
31	on the Wood, Iron or Steel "s Baker Standard"	Master	W J Stewart	YEAR	MONTH
TONNAGE:-	Built at Newcastle	By whom	Sir W G Armstrong Mitchell & Co. 1873.		
GROSS 3708	Owners European Petroleum Co Rd	Port belonging to	London		
UNDER D.K. 3335	Owners' Address (J Clark Mgr)				
NET 2375	(If not already recorded in Appendix to Register Book.)				
Surveyed Afloat off in Dry Dock		Name of Dock	Smiths	Destined Voyage	
WB=Cell DB or DBa	feet; uE&B	feet; f	feet;		
total capacity tons. H.P.T.	tons; A.P.T.	tons; M.T.	feet	tons.	

H.B.—All alterations in the existing records should be underlined.
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 52359 Port New

(Periodical Surveys, when held, must be reported in detail and variation in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the date and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? also whether any damage report was made, and, if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR Condition and alterations

Now done:- Vessel examined in dry dock, bottom found good cleaned & coated
Alterations, Two hatches each side on Spar deck in way of wing spaces aft have been heightened to 5'-0 above deck, to form expansion trunks to wing tanks which are now to be used as summer tanks. The watertight bulkhead on 93 frame has been additionally stiffened by fitting one extra vertical stiffener brackets fitted on all stiffeners at top & bottom, the partial bulkhead on 65 frame has been made airtight and an additional bulkhead fitted on frame thus forming a cofferdam. The tanks were tested with water to a height of hatches and found tight and efficient

The Superintendent (Mr. Eales) was asked to submit a plan showing

TYPE OF DAMAGE REPAIRS:-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
swed								
Removed and Fair'd or Repaired				✓				
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	Good	Stringers	✓	Dblng. Plates under Sounding Pipes	✓	Copper, or Y.M. of Wood Vessels (State if on Felt.)
Decks	"	Inner Bottom Plating	✓	Engine Room Skylights	✓ good	When put on, Month Year
Caulking of Decks	"	State if Tanks have been examined inside	✓	Coal Bunkers, Open'gs, Lids, &c.	✓	Boats
Watervays	"	State if Tanks now tested	Summer tanks only	Scuppers	✓	Masts, Yards, &c.
Coamings	"	Bulkheads	✓	Cargo Hatchways	✓	Condition, how ascertained
Beams & Fastenings	where seen "	Ceiling	✓	Hatches	✓	(State if wedges removed)
Outside Plating	"	Cement or Asphalt (State which.)	✓	Planking of Wood Vessels	✓	Sails
Caulking of ditto	"	Rudder	good	Caulking ditto	✓	Equipment letter
Rivets	"	Windlass	"	Treenails ditto	✓	Anchors, No. of
Breasthooks & Crutches	✓	Have Pumps now been examined and found effi-	cient?	Breasthooks & Stemson ditto	✓	Cables (State if now ranged)
Transoms	✓	Have Sluice Valves now been examined and found effi-	cient?	Transoms, Pointers, & Crutches ditto	✓	" length (on board)
Frames	where seen "	Have Watertight Doors now been examined and found effi-	cient?	Timbers of Frame at openings ditto	✓	" Rule length (per Table 22)
Reverse Frames	" "			Ditto ditto at other places ditto	✓	Hawsers & Warps
Floors	✓			Stringers, Clamps & Shelves ditto	✓	Standing & Running Rigging
Keelsons	✓			Salting ditto	✓	good

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1908," or "to remain as classed and to have record of survey, 1908, and the notations of as No. 1-98 and pIND98, &c."

This vessel is eligible in my opinion to remain as classed and to have record of Survey, 1907, subject to additional stiffening being fitted on bulkhead at end of summer tanks on the first occasion when vessel is steamed out

Office Fee (if chargeable) per Scale II, Sec. 27	£ 2	Fees applied for,	
Survey Fee (per Section 28)	£ 2	: : :	19
Special Damage or Repair Fee (if any) (per Sec. 26)	£	: : :	
Travelling Expenses (if chargeable)	£	: : :	19
Second Surveyor's Fee (if any)	£	: : :	

Committee's Minute
Character Assigned

FRI. 30 AUG. 1907

TUES. 3 SEP 1907

Surveyor to Lloyd's Register of British & Foreign Shipping.

FRI. 25 OCT 1907

TUES. 4 FEB 1908