

by Chief Ship Surveyor 14.1.15.

Received from Chief Ship Surveyor \_\_\_\_\_

SHIP'S NAME Stl.S.S. "BAKU STANDARD". Rpt. Gib. No 746

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey CONDITION. 2nd S.S.No.2, due 5,14.

The 2nd S.S.No.2 became due in May last and has been partly held.

A proposal to complete the survey within the year of grace was approved in June last. The Barry Surveyors recommended in June last that the main piece of rudder be examined at the No.2. The Gibraltar Surveyor now reports that two rudder pintles have been renewed and minor repairs effected.

The Surveyor recommends that the rudder head (which is worn and grooved at the glands) and the pintles, braces and other fittings be thoroughly examined at the next docking.

It is submitted action be deferred and the Owners informed accordingly.

*Handwritten signatures and dates:*  
14.1.15  
15