

Port GIBRALTAR,

31st December 1914.

**This is to Certify that I have**

*Surveyed the* repairs to Rudder of the British s.s. "BAKU STANDARD"  
carried out at this Port. The Rudder was worked in my presence with  
satisfactory result.

and that I have transmitted to the Committee of Lloyd's  
Register of British and Foreign Shipping, London, a Report,  
stating that all repairs recommended by me have been completed  
to my satisfaction, and that I have Recommended that she  
be continued as now classed.

Further recommend that on the next occasion of docking the  
Rudder head (which is worn and grooved at glands) pintles, braces and  
other fittings be thoroughly examined and any refit if then required  
be carried out.

being fit to carry dry and perishable cargo.

(Sgd) J.C. Talbot,

Engineer Commander R.N.,

for Ship & Engineer

Surveyor to Lloyd's Register.

& Lloyd's Agents - Gibraltar

This Certificate is issued upon the terms of the Rules and Regulations of the Society. While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracies or omissions in any Certificate issued by the Society or its Surveyors, or any entry in the Register Book or other publication of the Society, or for any accident, default, or negligence of the Surveyors, or other Officers of the Society.