

Admiralty Charter 7

by Chief Ship Surveyor 19.6.15

Received from Chief Ship Surveyor

L'S NAME Steel S. S. Baku Standard Rpt. Two No. 67649

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey DAMAGE AND PART S.S. No. 2

Vessel on Admiralty Charter

Damage through Heavy weather

(See Affx opt 746 795  
Gib 746  
Boy 14162)

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....	1						
Removed and faired or repaired.....							
Faired or repaired in place.....	2						

Other items:- Vessel examined in dry dock Bottom cleaned & coated  
Minor repairs effected

To complete - A few bolts in the after dk to be replaced with rivets

The 2<sup>nd</sup> S.S. No. 2 due S. 14 has also been partly held and the following repairs done due to wear and tear:- Rudder head, main piece & arms renewed.

A general examination of the vessel has been made and in the Surveyors opinion the proposal to complete survey in 6 months time. This vessel is on Admiralty Charter. *minutes approved*

It is proposed to complete the survey in 6 months time & this proposal, in the Surveyors opinion merits favourable consideration. It is submitted ~~this proposal might be approved and the vessel be~~ *action be deferred for the present.* ~~allowed to remain as classed~~ record of Survey, notation of

~~S.S. No. being deferred until completion of same.~~

The following remains to be done to complete the 2<sup>nd</sup> S.S. No. 2

z:- All the rule requirements to be complied with except  
of vessel in dry dock, Internal examination & testing of E.R. tank  
ging of the cables & examination of the rigging  
A few bolts in the after dk to be replaced with rivets.