

tested in accordance with this Society's requirements will be despatched by steamer to be placed on board the vessel on her arrival at Saluabana for which port she is bound.

The Spanker boom now temporarily repaired is considered efficient for the voyage, and the Owners representative states on the first opportunity permanent repairs will be made

pm

M.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT, EX STOCK.			WEIGHT OF STOCK.			TEST, PER CERTIFICATE.			WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons.	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.		
	1st Bower ...															
	2nd "															
	3rd "															
	Collective Weight.															
	Stream															
	Kedge.....															

* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

CHAIN CABLES.

Number of Certificate.	Length and size supplied.		Test per Certificate.		WEIGHT OF CHAIN CABLE.		Length and size per Rule.		Description.	Makers of Cables.	When and where tested and Superintendent.
	Length.	Diam.	Statutory.	Breaking.	Supplied.	Per Rule.	Length.	Diam.			
45937	150	2 1/8			360-1-20	353-3-0	150	2 3/16			
75938											
75939											
75940											
75941											
75942											
75943											
75944											
75945											
75946											
75947											
75948											
75949											
75950											
75951											
75952											
75953											
75954											
75955											
75956											
75957											
75958											
75959											
75960											
75961											
75962											
75963											
75964											
75965											
75966											
75967											
75968											
75969											
75970											
75971											
75972											
75973											
75974											
75975											
75976											
75977											
75978											
75979											
75980											
75981											
75982											
75983											
75984											
75985											
75986											
75987											
75988											
75989											
75990											
75991											
75992											
75993											
75994											
75995											
75996											
75997											
75998											
75999											
76000											

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.