

"PAMIR"

In view of the shell plating not having been drill tested at the last Special Survey, the vessel being then over 36 years old and that this is still outstanding and long overdue, arrangements should be made for the plating to be drilled in completion of the present survey. If, however, the Survey is otherwise completed, but it is not convenient to drill the plating this might be deferred until the end of the present emergency, in which case the notation of S.S. No.2 would require to be withheld and a record of "Examined (with date)" assigned in lieu. When the vessel is satisfactorily examined at the next annual dry docking a further 'Examined' record could be made.

IT IS SUBMITTED the Surveyor be informed.

10 C.S.
F.

6/11/44
5.6.44

See later
endorsement



© 2018

Lloyd's Register
Foundation