

of Mauretania

Nav report 52734

It is submitted the Surveyor should be requested to give the length on load line measured from fore side of rudder head to fore side of stem, as it is observed the load line length given on the report is 10.83 ft. greater than the Registered length.

The tonnage given on the report appears to be the tonnage including shelter deck space. The Surveyor should ascertain the under deck tonnage to the deck below the shelter deck. The tonnage coefficient given on the report as .82 is obviously incorrect for this vessel.

The usual formal application for freeboard assignment should be forwarded

J. H. C.      G. H. M.

22. 4. 07



© 2018

Lloyd's Register  
Foundation