

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor 24 SEP 1928VESSEL'S NAME Steel 4 Mast. Bk. "PASSAT" Rpt. \_\_\_\_\_ Rot. \_\_\_\_\_ No. 17764**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/22.)


Nature of Survey \_\_\_\_\_

This vessel has been placed in dry dock fully loaded on account of damage to bow plating through collision, and the following repairs carried out:- 4 shell plates renewed, 8 shell plates, 11 frames, 11 reverse frames and 1 beam repaired, starboard hawsepole renewed and minor repairs effected.

Some temporary repairs have also been carried out and the Surveyors recommend that permanent repairs be effected on the vessel's return from her present voyage.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject as recommended.

As now, subject etc.


  
22.9.28.


© 2018

Lloyd's Register  
Foundation