

5 "PASSAT" As recommended. I have to acquaint you that as a result  
a survey carried out at Buenos Aires in January last the class was  
subject to the hawsers and warps, etc. being brought up to Rule  
requirements, and to the repair of poop deck fittings being effected  
to the propulsion motor supercharger clutch being overhauled and  
determined on the ship's arrival from her present voyage at a European



Lloyd's Register  
Foundation

- 2 -

amburg (Cont'd.)

11th May, 1956.

port. I shall be glad if you will let me know what arrangements were  
made regarding these matters at this time.



© 2018

Lloyd's Register  
Foundation