

REPORT of SURVEY for REPAIRS.

IRON 3/390 2579

No. Supp 25 Survey held at London Date Oct 14th 1863
 on the S. "Kamsay" (Iron) Master J. H. White
 Tonnage 689 Built at Flamsey (Sellingham) When built 1863
 By whom built _____ Owners Coastfield &
 Port belonging to Liverpool Destined Voyage Otago
 If Surveyed Afloat or in Dry Dock Afloat off Greenhithe
 Last Survey, No. 3359 Port Iron Classified 12 A
 REPAIRS 63

A survey was requested on this vessel's stores which were found as stated below

Present Condition of the

Decks	Treenails	Windlass and Capstan <u>good</u>
Waterways	Breasthooks and Stemson	Pumps <u>3 of Iron</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>3 good</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>sufficient</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Sails <u>two suits</u>
Planksheers	Keelsons	Anchors No. of <u>3 x 1 x 2</u>
Sheerstrakes	Clamps and Shelves	Cables <u>270 fms 1 1/2</u>
Topsides	Ceiling	Hawsers and Warps <u>10 1/2 x 8 x 7 x 6 1/2 x 5</u>
Wales	Rudder	Standing & Running Rigging <u>manilla good</u>
Plank (Bottom) and Counter	Copper When put on _____	

General Observations and Opinion, _____
 Caulking of Bottom, Deck, & Waterways. _____

The testing certificates were promised to be forwarded to this office, which has not been done

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 13th November 1863

Character assigned 12 A 1

Thos W. Wain

