

# Report of Survey for Repairs, &c., of Engines and Boilers.

(Received at London Office)

WED, 28 JULY 1897

Date of writing Report	26 <sup>th</sup> July 1897	When handed in at Local Office	26 <sup>th</sup> July 1897	Port of Leith
No. in Reg. Book.	Survey held at 1 Leith		Date, First Survey	24 <sup>th</sup> July Last Survey
Tonnage	1066 on the Machinery of the Wood, Iron or Steel	Gross 889	S. S. Stettin	1897
Net	538	Vessel built at Glasgow	Master Robertson	YEAR MONTH
Registered Horse Power	98	Engines made at Leith	By whom Barclay Curle & Co When 1864 - 11	
No. of Main Boilers	1	Owners (J. Currie & Co Mys)	When 1889 Boilers, when made (Main) 1889 (Donkey) 1889	
No. of Donkey Boilers	1	Port Leith	Voyage Bremen	
Steam Pressure in Main Boilers	150 lbs	H Surveyed Afloat or in Dry Dock	Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).	
in Donkey Boilers	50 lbs	(State name of Dock.)	CHARACTER X for Special Survey. Date of last Survey and of Periodical Surveys.	

Last Survey No. 8349 Port Leith

## Particulars of Examination and Repairs (if any) Readjusting safety valves.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State briefly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarized at the end of the report. State also the dates and initials of any letters respecting this case.)

Has a Survey also been held on Ship?	If so, is the Report sent now, or when will it be sent?	Character of ship and Machinery previously seen in the Register Books.
No		Machinery and Boiler Surveyors (including date of N.B., if any).
		CHARACTER X for Special Survey. Date of last Survey and of Periodical Surveys.
		+ A 1 3, 97 SS 1st No. 3-12, 89 SS 1st No. 1-94
		+ N B 12, 89 BS 3, 97 Lmc 2, 94

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? No

Do. " Donkey " " No

If this was not done, state for what reasons? hot due

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler? No At what pressure were they afterwards adjusted under steam? 150 lbs

Did the Surveyor examine the Safety Valves of Donkey Boiler? No To what pressure were they afterwards adjusted? not adjusted

Has the propeller shaft been drawn and examined at this time? No If spare propeller shaft fitted, state whether new? ✓

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

The safety valves of main boilers adjusted at the working pressure of 150 lbs.

## General Observations, Opinion, and Recommendation:—

(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 0.95, B.A.M.S. 0.95 or 2.L.M.C. 0.95, 140 lbs., F.D., &c.)

as far as seen is now in good order + safe working condition + eligible in my opinion to remain as classed without fresh receipt of survey

Office or Registration Fee (per Sec. 27)	£ 1 1	Fees applied for
Survey Fee (per Section 28)	£ 1 1	1s
Special Damage Fee (per Section 28)	£ 1 1	
Travelling Expenses (if chargeable)	£ 1 1	Received by me, 1s

Thomas Field  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

\*State if Certificate is required

Committee's Minute

FRI 30 JUL 1897

Assigned

As now.

It is submitted that  
this message be copied to  
remain as REASSND.  
JW  
20/7/97

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much dampened as to spread the ink, or cause it to show through to the other side.

OF THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.