

Report of Survey for Repairs, &c., of Engines and Boilers.

MON. 30 APR 1900

(Received at London Office)

Date of writing Report *April 28 1900* When handed in at Local Office *April 28 1900* Port of *Leith*

No. in Reg. Book. *1165* Survey held at *Leith* Date, First Survey *April 18th* Last Survey *April 25th 1900*

on the Machinery of the Wood, Iron or Steel *1/2 Stettin* (No. of Visits *4*) Master *Taylor*

Tonnage Gross *889* Net *538* Vessel built at *Glasgow* By whom *Barclay Curle & Co* When *1864* MONTH *11*

Registered Horse Power *98* Engines made at *Leith* When *1889* Boilers, when made (Main) *1889* (Donkey) *1889*

No. of Main Boilers *1* Owners *J Currie & Co (Managers)* Port *Leith* Voyage *Baltic*

No. of Donkey Boilers *1* If Surveyed Afloat or in Dry Dock *Commercial dry dk.*

Steam Pressure— in Main Boilers *150* in Donkey Boilers *50*

(State name of Dock.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

CHARACTER for Special Survey, Date of last Survey and of Periodical Surveys.	Year assigned as original or revised.	Machinery and Boiler Surveys (including date of N.R., if any).
<i>十國 1. 3. 99.</i>		<i>L.M.C. 3. 98</i>
<i>SS Lth no 3. 12. 89</i>		<i>+ N.B. 12. 89</i>
<i>SS Lth no 2. 98</i>		<i>B.S. 4. 99.</i>

Last Survey No. _____ Port _____

Particulars of Examination and Repairs (if any) *B.S. Doc*

(Periodical Surveys, when held, must be reported in detail and variation in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.)

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? *yes*

Do. " Donkey " " " *yes*

If this was not done, state for what reasons? *✓*

And what parts of the Boilers could not be thus thoroughly examined? *✓*

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler? *✓*

Did the Surveyor examine the Safety Valves of the Main Boiler? *yes* To what pressure were they afterwards adjusted under steam? *150 lbs*

Did the Surveyor examine the Safety Valves of Donkey Boiler? *yes* To what pressure were they afterwards adjusted under steam? *50 lbs.*

Has the propeller shaft been drawn and examined at this time? *yes* If spare propeller shaft fitted, state whether new? *new shaft fitted.*

State the distance between lignum vitae of stern bush and top of after bearing of screw shaft? *close*

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done? *Complete.*

Doc Vessel placed in dry dock. Propeller shaft found fractured in body at butt of brass liners and spare shaft fitted in place of same. Propeller found cracked in boss and new propeller fitted. Fastenings of sea connections examined.

B.S. The main and donkey boilers examined internally and externally and safety valves of same examined and adjusted as above.

General Observations, Opinion, and Recommendation:— *The machinery of this vessel is now as far as seen in good and safe working condition and is eligible in my opinion to remain as classed and to have the record B.S. 4.00.*

Office or Registration Fee (per Sec. 27) £ _____

Survey Fee (per Section 24) £ *1. 7. 0*

Special Damage Fee (per Section 24) £ _____

Travelling Expenses (if chargeable) £ _____

Fees applied for *April 28 1900*

Received by me, *H. 5. 00*

Harry Clarke
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

THUR. 1 MAY 1900
B.S. 4.00.

Committee's Minute
Assigned

Has a Survey also been held on Ship? If so, is the Report sent now, or when will it be sent?

Insert Character of Ship and Machinery precisely as in the Register Book.

Certificate to be sent to

10,000—361,000—Drawing No.

Screw shaft renewed on acc. of
fracture rib-side at butt of
flues. Propellers renewed.

It is submitted that
this vessel is eligible for
THE RECORD, BSH.00

CM.
30.4.00

N.B.—If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.