

(Received at London Office THURS. 24 AUG 1905)

No. 11190.

~~REPORT of SURVEY for REPAIRS, &c.~~

Date of Writing Report 22 Aug

1905. When handed in at Local Office 23<sup>rd</sup> Aug 1905

THURS. 24 AUG 1905

No. in Reg. Book Survey held at Leith

1523 on the Wood, Iron or Steel S.S. "STETTIN" (No. of Visits) Last Survey 22<sup>nd</sup> Aug 1905.

Master Nalcorus

## TONNAGE:-

GROSS 876

UNDER D.K. 857

NET 528.

Built at Glasgow?

Owners J. Currie &amp; C.

Owners' Address

Port of Leith

Date, First Survey and

(No. of Visits)

Last Survey 22<sup>nd</sup> Aug 1905.

YEAR MONTH

When 1864 11

Port belonging to Leith

If not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Afloat Name of Dock

WB=Cell DB or Dba

feet; uE&amp;B

feet;

f

feet;

f

feet;

t

tons.

total capacity tons. F.P.T.

tons; A.P.T.

tons; M.T.

feet

t

tons.

Destined Voyage Hamburg.

Particulars of Classification (which must be inserted precisely as in Register Book &amp; Supplements).

CHARACTER.  
For Special Survey,  
Date of last Survey and of  
Periodical Surveys.Years  
Annuall  
Survey  
extinctMachinery and Boiler  
Surveys  
(including date of N.B., if any).

+ A. 1. 7-05

LM.C. 2-02

S.S. Ld. 11-03. 4-02

+ N.G. 12-89

B.S. 7-05

ND.G. 89

Society's Freeboard (if assigned) as  
painted on Ship and now verified

ft. in.

N.B.—All alterations in the existing records should be underlined.  
If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 1161 Port Leith

(Periodical Surveys, when held, must be reported in detail and variation in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? Damage unimportant also whether any damage report was made, and, if so, by whom? None.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Damage by Fire when crossing North Sea.  
Examined two oaks foul of Boiler space, 12 pieces of deck plank partly burnt, this has been renewed.

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:-
Renewed								
Removed and Fairied or Repaired								
Fairied or Repaired in place								

PRESENT CONDITION OF THE	Stringers	Boring. Plates under Sounding Pipes	Copper, or T.M. of Wood Vessels
Decks	Inner Bottom Plating	Engine Room Skylights	(State if on Felt.)
Caulking of Decks	State if Tanks have been examined inside	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Waterways	State if Tanks now tested	Scuppers	Boats
Coamings	Bulkheads	Gage Hatchways	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Hatches	Condition, how ascertained
Outside Plating	Cement or Asphalt (state which.)	Planking of Wood Vessels	(State if wedges removed)
Caulking of ditto	Rudder	Caulking ditto	Sails
Rivets	Windlass	Treenails ditto	Equipment letter
Breasthooks & Crutches	Have Clamps now been examined and found efficient?	Breasthooks & Stemson ditto	Anchors, No. of
Transoms	Have Sluice Valves now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Frames	Have Watertight Doors now been examined and found efficient?	Timbers of Frame at openings ditto	" length (on board) size
Reverse Frames		Ditto ditto at other places ditto	" Rule length (per Table 22) size
Floors		Stringers, Clamps & Shelves ditto	Hawsers & Warps
Keelsons		Salting (State if examined.) ditto	Standing & Running Rigging

## General Observations, Opinion as to Class, Recommendation, &amp;c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1-98," or "to remain as classed and to have record of survey, 1-98, and the notations of No. 1-28 and pND98, &amp;c."

This vessel is in good and efficient condition and eligible in my opinion to remain as classed without fresh record of survey.

Office Fee (if chargeable) per Scale II, Sec. 27 £	:	:	Fees applied for,
Survey Fee (per Section 28) £	:	:	19
Special Damage or Repair Fee (if any) £	:	:	Received by me,
(per Sec. 28)			19
Travelling Expenses (if chargeable) £	:	:	
Second Surveyor's Fee (if any) £	:	:	

S. D. Aikman

Surveyor to Lloyd's Register of British &amp; Foreign Shipping.