

Report of Survey for Repairs, &c., of Engines and Boilers.

Date of writing Report	19/9 1908	When handed in at Local Office	19/9 1908	Port of Lübeck	Received at London Office	21 SEP 1908
No. in Reg. Book	Survey held at Lübeck					
1709	on the Machinery of the Wood, Iron or Steel to Stettin					
Tonnage	Gross 876					
	Net 528					
Registered Horse Power	98					
No. of Main Boilers	1					
No. of Donkey Boilers	1					
Steam Pressure— in Main Boilers	150					
in Donkey Boilers	60					
Vessel built at Wismar						
Engines made at Lübeck						
Boilers, when made (Main) 1889						
Owners J. Currie & Co.						
If Surveyed Afloat or in Dry Dock Commercial Dry D.						
(State name of Dock.)						

Last Survey No. Port

Particulars of Examination and Repairs (if any) B.S.

Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be briefly summarised at the end of the report. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose, and why they were declined? also whether any damage report was made, and, if so, by whom?

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

Do. " Donkey " "

If this was not done, state for what reasons?

And what parts of the Boilers could not be thus thoroughly examined?

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

Did the Surveyor examine the Safety Valves of the Main Boiler?

Yes

To what pressure were they afterwards adjusted under steam? 150 lbs

Did the Surveyor examine the Safety Valves of Donkey Boiler?

Yes

To what pressure were they afterwards adjusted under steam? 50 lbs

Did the Surveyor examine all the manholes, doors and their fastenings of the Main Boilers?

Yes, and of the Donkey Boiler?

Yes

Did the Surveyor examine the drain plugs of the Main Boilers?

Some

, and of the Donkey Boiler?

None

Did the Surveyor examine all the mountings of the Main Boilers?

Yes

, and of the Donkey Boiler?

Yes

State the distance between lignum vite of stern bush and top of after bearing of screw shaft?

8

If the Survey is not complete state what arrangements have been made for its completion and what remains to be done?

Has screw shaft now been drawn and examined? Yes Is it fitted with continuous liner? No or two liners? Yes or is it without liners? —

Has shaft now been changed? No If so, state reasons —

Is the shaft now fitted new? — Has it a continuous liner? — or two liners? — or is it without liners? —

Propeller shaft drawn down and found satisfactory.
Propeller and fastenings in good order.

B.S. Main and donkey shafts examined throughout and found satisfactory
Centrifugal pump of main shaft set out being slightly displaced
on shaft but not in donkey shaft unmarked. All safety valves adjusted
I.P. cylinder skimmed out and new piston fitted. H.P. valve spindle
turned up and whitened.

General Observations, Opinion, and Recommendation:— The machinery of this vessel as
(State clearly what alteration, if any, is suggested to be made in the existing classification of the vessel's machinery in the Register Book, consequent upon this survey, and also
any alteration required to be made in the records of the vessel's machinery, boilers, working pressures, &c.; thus, for example, B.S. 9,00, B.A.M.S. 9,00, or X.L.M.C. 9,00,
140 lb. F.D., &c.)

far as I can see is now in good order and I think in my opinion to run in
as intended and to have wear of B.S. 9,00.

Office or Registration Fee (per Sec. 27). £ 1 - 10 -
Survey Fee (per Section 28). £ 1 - 10 -
Special Damage or Repair Fee (if any) (per Section 28). £ 1 - 7 -
Travelling Expenses (if chargeable). £ 1 - 7 -

Fees applied for
19/9 1908
Received by me,
30/9/08

M. A. Stark
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

* State if Certificate is required

Committee's Minute

TUES 22 SEP 1908

Assigned

B.S. 9,00

B Nil due 7.08 now held.
Minor repairs effected to
the machinery

Is it permitted that
this vessel is eligible for
TUG RECORD BS 9.08.

SWD
27/2/08

S. 9.08.

N.B.—If this Report is copied by Copying Press, special care must be taken that the copying paper is not so much dampened as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.